

### HCI Inventory of Pre-Owned Monoplace chamber Systems

#### ETC Baramed- Chambers for Sale

Latest Update: October 12, 2020 by SDR

Item Number	Model	Inside Diamter	Build Year	Panel Config.	Cycles	10 Year Seat/Seal Inspection Status	Computer Status	Window Status	Avail.	Notes	List Price	FOB
416-1	Baramed	30"	2000					Original	Now	As-is, No warranty, Warranty on request	\$31,000	NYC
416-2	Baramed	30"	2006	standard	4269	Seal Service in 2016		Original	Now	As-is, No warranty, Warranty on request	\$43,500	NYC
416-3	Baramed	30"	2005	reverse	3630	Seal Service in 2016		Original	Now	As-is, No warranty, Warranty on request	\$41,000	NYC
416-5	Adjustable Height Gurney for Baramed, Including Mattrees & Patient Tray (2 available)								Now	As-is, No warranty		
524-2	Baramed XD (Under Contract)	34"	2007	reverse	<5,000	Due	Original	Original	Now	180 day limited warranty (*)	\$29,500	SE US
532-1	Baramed XD	34"	2008			Due	IPC upgrade	Original	Now	180 day limited warranty (*)	\$32,000	South-central US
532-2	Baramed XD	34"	2008			Due	Orignal (Ampro)	Original	Now	180 day limited warranty (*)	\$29,000	South-central US
532-3	Baramed XD	34"	2009			Due	IPC upgrade	Original	Now	180 day limited warranty (*)	\$35,000	South-central US
532-4	Baramed XD	34"	2010			Due	Orignal (Ampro)	Original	Now	180 day limited warranty (*)	Call	South-central US
541-1	Baramed XD	34"	2010	standard		Due	Ampro. To be upgraded at sale	Original	Now	180 day limited warranty (*)	\$35,000	SE US
541-2	Baramed XD	34"	2011	reverse		Due 2021	Ampro. To be upgraded at sale	Original	Now	180 day limited warranty (*)	\$38,000	SE US
541-3	Baramed XD SELECT	34"	2007	reverse		Due	Panel PC. To be upgraded at sale	Original	Now	180 day limited warranty (*)	\$37,500	SE US
										(*) Requires post del'y PM by tech acceptable to HCI. If performed by HCI this is subject to separate pricing. International shipments are "as-is" at time of shipment. Warranties are normally parts only.		

**General Notes to ETC Listings:**

All chambers come with standard (non hydraulic) gurney unless indicated otherwise, patient tray and mattress  
 All chambers are built to PVHO-1, but not all are National Board stamped (newer ones are)  
 Maintenance records are available for most chambers  
 All chamber computers either have Windows based computer or have been upgraded as noted  
 All prices and technical details subject to change without notice.

**Specific Notes:**

## HCI Inventory of Pre-Owned Monoplace chamber Systems

### Sechrist Chambers for Sale

Latest Update: October 12, 2020 by SDR

Item Number	Model	Inside Diameter	Build Year Chamber/window	Control Panel Config.	Cycles	10 Year Seat/Seal Inspection Status	Computer Status	Window Status	Avail.	Notes	List Price	FOB	
TBD	2500B	25"	Various	std/reverse on request	0	Due in 2028	Pneumatic	New at shipment	14 wks	New window & seals at sale. Well suited for veterinary centers	\$43,000	Mid-Atlantic	
469-2	2500B	25"	~1990	Standard	N/A	Out of date window	Pneumatic	Original, Past 20 years	Now	No warranty except working at sale date	\$6,500	SE US	
490-1	2500B (Reduced)	25"	1987/2008	Standard	2,851	Due	Pneumatic	New in 2008	Now	Gurney sold separately	\$7,900	SE US	
490-2	2500B (Reduced)	25"	1993/2003	Reverse	3,293	Due	Pneumatic	New in 2003	Now	Gurney sold separately	\$6,900	SE US	
<b>Notes for above two chambers</b>													
1. Deduct \$1,000 per chamber if both chambers taken													
2. Gurney options:													
											Five wheel adjustable height ("hydraulic")	\$3,500	Mid-Atlantic
											Five wheel, fixed height	\$1,900	SE US
											Four wheel, chromed-steel frame	\$500	SE US
											Original blue frame gurney, shortened to 5'	\$4,200	Mid-Atlantic
531	2800 set up for air ventilation w/compressor	28"	2001	Standard	6,100	None	Pneumatic	Original	Now	180 day ltd warranty(*)	\$38,000 installed most locations	Southern CA	
522-1	3200, Blue	32"	2008	Standard	Note 1	None	Pneumatic	Original	Now	180 day limited warranty (*)	\$38,000	Northern US	
522-2	3200R, Blue	32"	2008	Reverse	Note 1	None	Pneumatic	Original	Now	180 day limited warranty (*)	\$38,000	Northern US	
441-2	3300E, Blue (under contract)	32"	2007	Standard	3359	None	Factory original	Original	Now	180 day limited warranty (*)	\$36,000	SE US	
552-1	3200, Blue (new listing)	32"	2009	Standard	<2,500	Due	Factory original	Original	Now	180 day limited warranty (*)	\$37,500	South Central US	
552-2	3200R, Blue (new listing)	32"	2009	Reverse	<2,500	Due	Factory original	Original	Now	180 day limited warranty (*)	\$37,500	South Central US	
544-1	3600ER	36"	2007	Reverse		None	Factory original	Original	Now	180 day limited warranty (*)	\$39,500	NW US	
545-1	3600ER, Blue (new listing)	36"	2009	Reverse		None	Factory original	Original	Now	180 day limited warranty (*)	\$41,500	Mid-Atlantic	
<b>Notes:</b>													
1	Cylce counter value is inflated due to 1.5 psig ear clearing maneuvers when diving children. Cycle counter reads 19,000+, but number of maningful cyclces is believed to be about 12,000.												
(*) Requires post del'y PM acceptable to HCI. If performed by HCI this is subject to separate pricing. International shipments are "as-is" at time of shipment. Warranties are normally parts only.													

**General Notes to Sechrist Listings:**

All chambers come with standard (non hydraulic) gurney unless indicated otherwise, patient tray and mattress  
 All chambers are built to PVHO-1, and all are National Board stamped except for some 2500 series chamber built in the early 1980s  
 Maintenance records are available for most chambers  
 All prices and technical details subject to change without notice.

### HCI Inventory of Pre-Owned Monoplace chamber Systems

#### Perry Chambers for sale

Latest Update: October 12, 2020 by SDR

Item Number	Model	Inside Diameter	Build Year	Control Panel Config.	Cycles	10 Year Seat/Seal Inspection Status	Computer Status	Window Status	Avail.	Notes	List Price	FOB
507-1	Sigma 40	40"	2008	Standard (left)	3,005	due	Pneumatic	Original	Call	180 day limited warranty (1)	TBD	SE US
507-2	Sigma 40	40"	2008	Reverse (Right)	2,705	due	Pneumatic	Original	Call	180 day limited warranty (1)	TBD	SE US
				<b>Chamber Specific Notes:</b> 1. Requires post del'y installation and PM by tech acceptable to HCI. Cost is \$2,400 per chamber if performed by HCI. 2. Requires post delivey set-up and check-out by Perry Technician. Cost is \$7,800 These chambers are best sold as a "matched pair".								

**General Notes to Perry Listings:**

All chambers come with standard (non hydraulic) gurney unless inidcated otherwise, patient tray and mattress  
 All chambers are built to PVHO-1 and are National Board stamped  
 Maintenance records are available for most chambers  
 All prices and technical details subject to change without notice.

### HCI Inventory of Pre-Owned Monoplace chamber Systems

#### PAHI Chambers for sale

Latest Update: October 12, 2020 by SDR

Item Number	Model	Inside Diameter	Build Year Chamber/window	Door Opens to	Cycles	10 Year Seat/Seal Inspection Status	Computer Status	Window Status	Avail.	Notes	List Price	FOB
551-1	PAHI S1, Tan	32"	2009	Left	5,100	Done, PVHO-2 Case 1	Pneumatic	Original	Now	180 day limited warranty (1)	\$39,500	Mid Atlantic
551-2	PAHI S1, Tan	32"	2009	Right	5,100	Done, PVHO-2 Case 1	Pneumatic	Original	Now	180 day limited warranty (1)	\$39,500	Mid Atlantic
552-1	PAHI S1, Tan	32"	2011	Left	<2000	due	Pneumatic	Original	Now	180 day limited warranty (1)	\$45,000	Texas
552-2	PAHI S1, Tan	32"	2011	Right	<2000	due	Pneumatic	Original	Now	180 day limited warranty (1)	\$45,000	Texas

**General Notes to PAHI Listings:**

All chambers come with adjustable height gurney patient tray and mattress and chamber top mounted TV  
 All chambers are built to PVHO-1 and are National Board stamped  
 Maintenance records are available for most chambers  
 All prices and technical details subject to change without notice.

### HCI Inventory of Pre-Owned Monoplace chamber Systems

#### HYOX HTU2- Chambers for sale

Latest Update: October 12, 2020 by SDR

Item Number	Model	Inside Diamter	Build Year	Control Panel Config.	Cycles	10 Year Seat/Seal Inspection Status	Computer Status	Window Status	Avail.	Notes	List Price	FOB
510-1	HTU2 with RSI ODS-1 Hood & Mask Breathing System	N/A	1987	Standard See Photos	N/A	Due	Not applicable	New in 2007	Now	Refurbished & Upgraded to include new windows & Reimers Systems ODS-1 Oxygen Delivery System , Incl in 2007	Call	Lorton, VA
Maintenance support for thses chambers is offerecd by Reimers Systems Division, PCCI, Inc., <a href="http://www.reimerssystems.com">www.reimerssystems.com</a>												
A standard annual PM normally runes about \$2,500 per chamber. A set of replacement windows installed at a PM is about a \$14,500 adder.												

**General Notes to HTU2 Listings:**

All chambers come with built-in patient chair that telescopes out for loading.  
 Maintenance records are available for most chambers  
 All prices and techncial details subject to change without notice.