703-863-3871

sdreimers1968@gmail.com



### General Comments <u>to</u> Availability Notice Pages S. D. Reimers, December 3, 2025

- 1. We have added a new way of communicating our ranking the estimated values of the chambers we are offering. It is shown in the right-hand column of the page for most manufacturers under the heading of "Cost per year or remaining window life". Those figures are based on dividing the chamber price listed by the number of years remaining in the PVHO-2 rated 20-year window life after subtracting from the listed price an estimated salvage value of 5% of new chamber price. For the chambers that we wish to draw attention to in this regard, the corresponding cell in the column titled cost per year of remaining window life is shown with a light blue fill color.
- 2. Other chambers may also be excellent values under certain circumstances. One such circumstance is start-up situations where initial cost is the dominant concern and third-party financing is difficult. See items 568-11A and 568-12A on the ETC page. Once a facility is operating and profitable for 2 to 3 years, third party financing options make higher acquisition costs much easier. Many of the chambers that are offered with only a few years' rated window life remaining are also offered with a pre-packaged option for re-windowing the chamber when required. This approach can result in some stunningly low values for cost per year of useful window life. Re-windowing services are offered for all ETC, Sechirst, PAHI and Marine Dynamics chambers.

r

Stephen Reimers

333

### **Inventory of Pre-Owned Monoplace Chamber Systems**

703-863-3871

sdreimers1968@gmail.com

Cost per year of remaining window life, Salvage Value =5% of new price

### **ETC Baramed- Chambers for Sale**

### Latest Update: December 4, 2025 by SDR

Item No.	Model		Inside Diamter	Build Year	Window Year	Panel Config.	Cycles	Seat/Seal Inspection	Computer Status	Window Status	Avail.	Notes	List Price	FOB
675-3	white	Off-	34"	2010	2010			Due		Original	Now		\$30,000	Provisional<<- -Call
675-4	white	Off-	34"	2009	2026			Due		New at Sale	16 wks	3. Available only with new window	\$56,500	Provisional<<- -Call
568-11	BaraMed XD ( white	Off-	34"	2007	2007	Standard (left)		Due	Includes all ETC upgrades	Original	Now	1,3,4,5	\$24,000	NE US
568-11A	BaraMed XD ( white	Off-	34"	2007	2027	Standard (left)	<10	Due	Includes all ETC upgrades	Original	Now	1,3,4,5,7	\$78,000	NE US
568-12	BaraMed XD ( white	Off-	34"	2007	2007	Reverse (Right)		Due	Includes all ETC upgrades	Original	Now	1,3,4,5	\$24,000	NE US
568-12A	BaraMed XD ( white	Off-	34"	2007	2027	Reverse (Right)	<10	Due	Includes all ETC upgrades	Original	Now	1,3,4,5,7	\$78,000	NE US
699-1	BaraMed Select ( white	Off-	34"	2016	2016	Standard (left)	<3,000	Due		Original	Now	1,3,4,5	\$49,500	Mid-West
699-2	BaraMed Select (	Off-	34"	2016	2016	Reverse (Right)	<3,000	Due		Original	Now	1,3,4,5	\$49,500	Mid-West
699-3	BaraMed Select ( white	Off-	34"	2016	2016	Standard (left)	Call	Due		Original	Jan 26	1,3,4 In service until Jan 2026	\$49,500	Mid-West
699-4	BaraMed Select ( white	Off-	34"	2016	2016	Reverse (Right)	Call	Due		Original	Jan 26	1,3,4 In service until Jan 2026	\$49,500	Mid-West
664-1	COMPLETE SYST ETC, BaraMed X Off-white		34"	2007	2007	Standard (left)	1,087	Due	Updated by ETC	Original	Now	Includes air plant and O2 concentrator. Complete system	\$71,000	Southern CA

1. Requires post del'y PM by tech acceptable to Seller. If performed by Seller this is subject to separate pricing.

#### **General Notes to ETC Listings:**

All chambers come with standard (non hydraulic) gurney unless indicated otherwise, patient tray and mattress

All chambers are built to PVHO-1, but not all are National Board stamped (newer ones are)

Maintenance records are available for most chambers

All chamber computers either have Windows based computer or have been upgraded as noted

All prices and technical details subject to change without notice.

\$5,000 \$2,536 \$9,500 \$3,318 \$9,500 \$3,318 \$4,045 \$4,045

\$33,000

<sup>2.</sup> Incluces chamger top TVs and mounts

<sup>3.</sup> Re-windowing serivce is available. Lead time is 16 weeks. Price is \$35000 for one chamber, \$30,000 each if done two or more at one time.

<sup>4.</sup> Maintained by Liberty Medical Systems (LMS). LMS was part of the original development & production team for ETC. The are capable of handling any isses that may arise..

<sup>5</sup> Less than 6 weeks our of active service.

<sup>6.</sup> Price includes on-site re-window serivce in 2027. Cost of new window not due until 150 days prior to installation

<sup>7,</sup> For re-window dates 12 months or more from date of sale, final price may be adjsted as needed to accommodate changes in window dosts.

sdreimers1968@gmail.com

# **Inventory of Pre-Owned Monoplace Chamber Systems**

703-863-3871

Cost per year of remaining window life, Salvage Value =5% of new price

	<b>Sechrist Cham</b>	bers for	Sale					Latest Upda	ate: Dece	ember 3	3, 2025 by SDR			
Item No.	Model	Inside Diamter	Build Year	Window Year	Control Panel	Cycles	10 Year Seat/Seal	Computer & Gurney	Window Status	Avail.	Notes	List Price	FOB	
675-1	NEW LISTING 3200H, Blue	32.5	2007	2007	Standard	<5,200	Due	Pneumatic	Originnal	1-3 wks	Working at ship date Notes 1 ,4	\$17,500	Provisional<< -Call	\$6,250
675-2	NEW LISTING 3200HR, BLue	32.5	2007	2007	Reverse	<4,200	Due	Pneumatic	Originnal	1-3 wks	Working at ship date Notes 1 ,4	\$17,500	Provisional<< -Call	\$6,250
667-9	NEW LISTING 3200H, Blue	32.5	2006	2006	<10,500	<10,500	Due	Pneumatic	Originnal	Jan 2026	Working at ship date Notes 1,4	\$10,500	Call	\$5,500
667-10	NEW LISTING 3200HR, BLue	32.5	2006	2006	Reverse	<10,300	Due	Pneumatic	Originnal	Jan 2026	Working at ship date Notes 1,4	\$10,500	Call	\$5,500
694-1	NEW LISTING 3200H, BLue	32.5	2008	2008	Standard	<1,200	Due	Pneumatic	Originnal	Now	Working at ship date Notes 1,4	\$16,000	Central US	\$3,667
667-1	Under Contract 3300H, BLue	32.5	2018	2018	Standard	1881		Pneumatic	Originnal	1-3 wks	WITHDRAWN	\$48,500	NW US	\$3,308
667-2	NEW LISTING 3300HR, BLue	32.5	2018	2018	Reverse	12436		Pneumatic	Originnal	1-3 wks	Working at ship date Notes 1 ,4	\$49,500	Central US	\$3,385
667-3	Under Contract 3300H, BLue	32.5	2019	2019	Standard	6798		Pneumatic	Originnal	1-3 wks	UNDER CONTRACT	\$57,000	Central US	\$3,671
667-4	3300HR, BLue	32.5	2019	2019	Reverse	2,956		Pneumatic	Originnal	1-3 wks	SOLD	\$59,000	Central US	\$3,814
667-5	3300H, BLue	32.5	2018	2018	Standard	8,762		Pneumatic	Originnal	1-3 wks	SOLD	\$44,500	Central US	\$3,000
667-6	NEW LISTING 3300HR, BLue	32.5	2022	2022	Reverse	2,212		Pneumatic	Originnal	1-3 wks	UNDER CONTRACT	\$67,200	Central US	\$3,624
667-7	NEW LISTING 3300H, BLue	32.5	2021	2021	Standard	1,675			Originnal	1-3 wks	Working at ship date Notes 1 ,4	\$67,200	Central US	\$3,850
667-8	3300HR, BLue	32.5	2022	2022	Reverse	1,213		Pneumatic	Originnal	1-3 wks	SOLD	\$72,800	Central US	\$3,953
607-4	NEW LISTING 3300HRwS, Blue	32.5"	2018	2018	Reverse	500	Due	Pneumatic	Original	3-4 wks	Notes 1 ,4 Garage Gurney	\$69,500	Virginia	\$4,885
694-3	NEW LISTING 3600H, Blue	36"	2010	2010			Due	Pneumatic	Original	Call	Working at del'y date Notes 1 ,4	\$45,000	Oklahom\	\$7,800
695-1	NEW LISTING 3600H, Blue	36"	2010	2010	Standard	<7000	Due	Pneumatic	Original	Call	Working at del'y date Notes 1 ,4	\$51,500	SW US	\$9,100
695-2	NEW LISTING 3600HR, Blue	36"	2010	2010	Reverse	<7000	Due	Pneumatic	Original	Call	Working at del'y date Notes 1 ,4	\$51,500	SW US	\$9,100
682-1	3600E	36"	2009	2009	Standard	7,091	Due	Computer Controlled	Original Computer	1-3 wks	Working at del'y date Notes 1 ,4	\$31,000	Provisional< <call< td=""><td>\$6,250</td></call<>	\$6,250
682-2	3600ER	36"	2009	2009	Reverse	3,090	Due	Computer Controlled	Original Computer	1-3 wks	Working at del'y date Notes 1 ,4	\$31,000	Provisional<< -Call	\$6,250

For More Info:

Stephen Reimers

703-863-3871

Inventory of Pre-Owned Monoplace Chamber Systems

3333

sdreimers1968@gmail.com

		c 0c	oop	iacc cita		,						suremiers1500@g	man.com
694-2	3600E	36"	2008	2008			Due	Computer Controlled	Original Computer	1-3 wks	Working at del'y date Notes 1 ,4	\$22,500	Oklahoma
607-5	Under Contract 3600H, Blue	36"	2018	2018	Standard	500	Due	Pneumatic	Original	2 wks	Working at del'y date Notes 1 ,4	\$82,000	Virginia
585-1	3600E, Blue	36"	2009	2009	Standard	<1,000	Due	Computer Controlled	Original	Now	Note 1	28000	Florida
585-2	3600E, Blue	36"	2009	2009	Reverse	<1,000		Computer Controlled	Original	Now	Note 1	28000	Florida

\$5,500
\$5,846
\$5,500
\$5,500

#### Specific Notes

### **General Notes to Sechrist Listings:**

All chambers come with standard (non hydraulic) gurney unless indicated otherwise, patient tray and mattress

<sup>1.</sup> Age less than 20 years, 180 day limited warranty. Requires post del'y PM acceptable to Seller. If performed by Seller this is subject to separate pricing. Otherwise, no warranty.

<sup>2.</sup> In daily use until Dec. 20, 2023. Obvious crazing patent foot end of chamber on both chambers. However, not so severe that the chamber could not remain in service. If sold with current window (price on request,

<sup>3.</sup> With new window, prices is about \$65,000 additional FOB destination, valid for most mainland US locations. Delivery lead time is 20 to 24 weeks

<sup>4.</sup> Price shown is for chamber complete & in working order. Add \$3,000 for pre-shipment service and report thereof.

Stephen Reimers

3333

### **Inventory of Pre-Owned Monoplace Chamber Systems**

703-863-3871

sdreimers1968@gmail.com

	Perry Chambe	rs for sal	le		Latest Update: December 3, 2025 by SDR									
Item Number	Model	Inside Diameter	Build Year	Window Year	Control Panel Config.	Cycles	Seat/Seal Inspection Status	Computer Status	Window Status	Avail.	Notes	List Price	FOB	
	PRICE REDUCTION				Reverse						180 day limited warranty			
583-1	Sigma 34	34"	2007	2007	(Right)	TBD	Completed	Pneumatic	Original	Call	(1)	\$19,000	Ontario	\$7,000
583-1	Sigma 34	34"	2006	2006	Reverse (Right)	TBD	Completed	Pneumatic	Original	Call	180 day limited warranty (1)	\$14,000	West Coast	\$8,400
					Reverse						180 day limited warranty			
583-2	Sigma 34	34"	2006	2006	(Right)	TBD	Completed	Pneumatic	Original	Call	(1)	\$14,000	West Coast	\$8,400
689-1	Sigma 34	34"	2003	2003	Standard	TBD		Pneumatic	Original	lmm	Note 6, Call	Call	Texas	N/A
689-2	Sigma 34	34"	2003	2003	Reverse	TBD		Pneumatic	Original	lmm	Note 6, Call	Call	Texas	N/A
689-3	Sigma 34	34"	2006	2006	Standard	TBD		Pneumatic	Original	lmm	Note 6, Call	Call	Texas	
689-4	Sigma 34	34"	2006	2006	Reverse	TBD		Pneumatic	Original	lmm	Note 6, Call	Call	Texas	
679-1	Sigma 34 White	34"	2006	2006	Standard	TBD	Due	Working	Original	Now	Note 6, Call	\$20,000		\$15,000
689-5	Sigma 34 White	34"	2003	2003	Reverse	4,919		Pneumatic	Original	lmm	UNDER CONTRACT	\$4,500	Louisiana	N/A
689-6	Sigma 34 White	34"	2006	2006	Standard	4,947		Pneumatic	Original	lmm	UNDER CONTRACT	\$9,000	Louisiana	\$4,000
689-7	Sigma 34 White	34"	2006	2006	Reverse	7,040		Pneumatic	Original	lmm	UNDER CONTRACT	\$9,000	Louisiana	\$4,000
694-3	Sigma 34 White	34"	2007	2007	Standard	TBD		Pneumatic	Original	Call	1,2,6	\$14,250	Oklahoma	\$4,625
634-7	Sigma 34, Fully Rebuilt	34"	Various	2026	TBD	0	N/A	Pneumatic	New at shipment	10-16 wks	180 day limited warranty (1)	\$90,000	Provisional< <call< td=""><td>\$4,048</td></call<>	\$4,048
634-5	Sigma PLUS 40 Fully Rebuilt	40"	Various	2026	TBD	0	N/A	Pneumatic	New at shipment	10-16 wks	180 day limited warranty (1)	\$99,000	Provisional<<	\$4,381
583-2	Sigma 40 REDUCED	40"	2017	2017	Reverse (Right)	very low	Due 2027	Pneumatic	Original	Call	180 day limited warranty (1)	\$72,000	Ontario	\$5,417

### Specific Notes

1. 180 day limited warranty. Requires post del'y PM acceptable to Seller. If performed by Seller this is subject to separate pricing.

6. With new window, price is approx. \$65,000 additional FOB destination, valid for most mainland US locations. Delivery lead time is 20 to 24 weeks

### **General Notes to Perry Listings:**

All chambers come with standard (non hydraulic) gurney unless indicated otherwise, patient tray and mattress

All chambers are built to PVHO-1 and are National Board stamped

Maintenance records are available for most chambers

All prices and technical details subject to change without notice.

Cost per year of remaining window life, Salvage Value =5% of new price

<sup>2.</sup> Price shown is for chamber in complete working oared. Add \$2,000 for pre-shipment service and report thereof.

Stephen Reimers

3333

# **Inventory of Pre-Owned Monoplace Chamber Systems**

703-863-3871 sdreimers1968@gmail.com

### **HYOX HTU2- Chambers for sale**

# Latest Update: December 3, 2025 by SDR

Model	Inside Diameter	Build Year	Window Year	Door	Cycles	10 Year Seat/Seal Inspection Status	Computer Status	Window Status	Avail.	Notes	List Price	FOB
HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP	N/A	1999	2021	Standard See Photos	N/A	Due 2031	Not applicable	New in 2021	Now	Upgraded 2005 to Include RSI ODS-1 Breathing System, Overhauled Jan 2021 with new windows.	\$63,000	Northern Virginia
HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP	N/A	2004	2004	Standard See Photos	N/A	Done	Not applicable	New in 2004	Now	Upgraded 2005 to Include RSI ODS-1 Breathing System, Overhauled Jan 2021	\$44,000	Northern Virginia
HTU2 with original Scott Mask Breathing System 2.0 ATA MAWP	N/A	Call	Call	Standard See Photos	N/A	Not done	Not applicable	Original	Now	Original out fitting. Original built-in air compressor removed, but still available.	Call	New England
HTU2 with RSI Control System Upgrade, 2.0 ATA MAWP	N/A	1995	1995	Standard See Photos	N/A	Due 2029	Not applicable		Now	Includes air plant but no O2 service or patient breathing system	REDUCED \$35,000	Los Angeles
Basic HTU2	N/A		Call	Standard See Photos	N/A	Due 2029	Not applicable	Original	Now		Call	Oklahoma
	HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP 2.0  HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP 2.0  HTU2 with original Scott Mask Breathing System 2.0 ATA MAWP  HTU2 with RSI Control System Upgrade, 2.0 ATA MAWP	Model Diameter  HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP  HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP  HTU2 with original Scott Mask Breathing System 2.0 ATA MAWP  HTU2 with RSI Control System Upgrade, 2.0 ATA MAWP	Model         Diameter         Build Year           HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP         N/A         1999           HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP         N/A         2004           HTU2 with original Scott Mask Breathing System 2.0 ATA MAWP         N/A         Call           HTU2 with RSI Control System Upgrade, 2.0 ATA MAWP         N/A         1995           Basic HTU2         N/A         N/A	Model         Diameter         Build Year         Year           HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP         N/A         1999         2021           HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP         N/A         2004         2004           HTU2 with original Scott Mask Breathing System 2.0 ATA MAWP         N/A         Call         Call           HTU2 with RSI Control System Upgrade, 2.0 ATA MAWP         N/A         1995         1995           Basic HTU2         N/A         Call         Call	Model     Diameter     Build Year     Year     Door       HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP     N/A     1999     2021     Standard See Photos       HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP     N/A     2004     2004     Standard See Photos       HTU2 with original System 2.0 ATA MAWP     N/A     Call     Call     Standard See Photos       HTU2 with RSI Control System Upgrade, 2.0 ATA MAWP     N/A     1995     1995     Standard See Photos       HTU2 with RSI Control System Upgrade, 2.0 ATA MAWP     N/A     1995     1995     Standard See Photos       Basic HTU2     N/A     Call     Standard See Photos	Model         Diameter         Build Year         Year         Door         Cycles           HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP         N/A         1999         2021         Standard See Photos         N/A           HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWP         N/A         2004         2004         Standard See Photos         N/A           HTU2 with original System 2.0 ATA MAWP         N/A         Call         Call         Standard See Photos         N/A           HTU2 with RSI Control System Upgrade, 2.0 ATA MAWP         N/A         1995         1995         Standard See Photos         N/A           Basic HTU2         N/A         Call         Standard See Photos         N/A	ModelInside DiameterBuild YearWindow YearDoorCyclesSeat/Seal Inspection StatusHTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWPN/A19992021Standard See PhotosN/ADue 2031HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWPN/A2004Standard See PhotosN/ADoneHTU2 with original System 2.0 ATA MAWPN/ACallCallStandard See PhotosN/ANot doneHTU2 with RSI Control System Upgrade, 2.0 ATA MAWPN/A1995Standard See PhotosN/ADue 2029Basic HTU2N/ACallStandard See PhotosN/ADue 2029	ModelInside DiameterBuild YearWindow YearDoorCyclesSeat/Seal Inspection StatusComputer StatusHTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWPN/A19992021Standard See PhotosN/ADue 2031Not applicableHTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWPN/A2004Standard See PhotosN/ADoneNot applicableHTU2 with original System 2.0 ATA MAWPN/ACallCallStandard See PhotosN/ANot doneNot applicableHTU2 with RSI Control System Upgrade, 2.0 ATA MAWPN/A19951995Standard See PhotosN/ADue 2029Not applicableBasic HTU2N/ACallStandard See PhotosN/ADue 2029Not applicable	ModelInside DiameterWindow Poor DoorCyclesSeat/Seal Inspection StatusComputer StatusWindow StatusHTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWPN/A19992021Standard See PhotosN/ADue 2031Not applicableNew in 2021HTU2 with RSI ODS-1 Hood & Mask Breathing System 2.0 ATA MAWPN/A2004Standard See PhotosN/ADoneNot applicableNew in 2004HTU2 with original System 2.0 ATA MAWPN/ACallStandard See PhotosN/ANot doneNot applicableOriginalHTU2 with RSI Control System Upgrade, 2.0 ATA MAWPN/A19951995Standard See PhotosN/ADue 2029Not applicableOriginalBasic HTU2N/ACallStandard See PhotosN/ADue 2029Not applicableOriginal	ModelInside DiameterBuild YearWindow YearDoorCyclesSeat/Seal Inspection StatusComputer StatusWindow StatusHTU2 with RSI ODS-1 HOOd & Mask Breathing System 2.0 ATA MAWPN/A19992021Standard See PhotosN/ADue 2031Not applicableNew in 2021Now in 2021HTU2 with RSI ODS-1 HOOd & Mask Breathing System 2.0 ATA MAWPN/A20042004Standard See PhotosN/ADoneNot applicableNew in 2004Now in 2004HTU2 with original System 2.0 ATA MAWPN/ACallStandard See PhotosN/ANot doneNot applicableOriginalNow in 2004HTU2 with RSI Control System Upgrade, 2.0 ATA MAWPN/A19951995Standard See PhotosN/ADue 2029Not applicableOriginalNow in 2004Basic HTU2N/ACallStandard See PhotosN/ADue 2029Not applicableOriginalNow in 2004	HTU2 with RSI ODS-1 HOOd & Mask Breathing System 2.0 ATA MAWP   LTU2 with Original Scott Mask Breathing System 2.0 ATA MAW	Inside Diameter   Build Year   Door   Cycles   Status   Status

General Notes to HTU2 Listings:

All chambers come with built-in patient chair that telescopes out for loading.

All prices and technical details subject to change without notice.

r

sdreimers1968@gmail.com

703-863-3871

# **Inventory of Pre-Owned Monoplace Chamber Systems**

**PAHI Chambers for sale** 

PAIR

PAHI-S1 Right Hinged Door



-00

**PAHI-S1 Left Hinded Door** 

Cost per year of remaining window life, Salvage Value =5% of new price

N/A \$3,000 \$7,500 \$4,679 \$4,679 \$5,375 \$5,375

# Latest Update: December 3, 2025 by SDR

Item Number 579-1	Model & Color PAHI S1-3200, Tan	Inside Dia.	Build Year	Window Year 2004	Door Opens to Left	Cycles 7,572	10 Year Seat/Seal Inspection Status	Computer Status Pneumatic	Window Status Original	<b>Avail.</b> Call	Notes Needs repairs	List Price	FOB Oklahoma
579-1	PAHI S1-3200, Tan	32"	2008	2025	Left	7,572	Due	Pneumatic	New at sale	16 wks	Built 2004, new window prior to shipment	\$65,000	Texas
607-4	PAHI S1-3200, Tan	32"	2008	2008	Left	5,800	Due	Pneumatic	Original	Sold	4.0	SOLD	Virginia
607-5	PAHI S1-3200', Tan	32"	2008	2008	Right	6,000	Due	Pneumatic	Original	2 wks	1, 3	\$27,500	Virginia
691C-1	PAHI S1-3200', Tan	32"	2012	2012	Left	4,518	Due	Pneumatic	Original	2-4 wks	1, 2	\$38,000	No. Illinois
691C-2	PAHI S1-3200', Tan	32"	2012	2012	Right	5,136	Due	Pneumatic	Original	2-4 wks	1, 2	\$38,000	No. Illinois
691C-3	PAHI S1-3200', Tan	32"	2007	2007	Left	Call	Due	Pneumatic	Original	2-4 wks	1, 2	\$16,000	No. Illinois
691C-4	PAHI S1-3200', Tan	32"	2007	2007	Right	4,,492	Due	Pneumatic	Original	2-4 wks	1, 2	\$16,000	No. Illinois
Notes:	1. 180 day limited warr	anty. Require	s post del'y in	stallation and	PM by tech	acceptable	to Seller.					·	
	<ol><li>Chamber has a Can</li></ol>	adian Regtrat	tion Number,	Therefore sho	old be accept	able for use	e in Canada.					·	

General Notes to PAHI Listings:

All chambers come with adjustable height gurney patient tray and mattress and chamber top mounted TV

All chambers are built to PVHO-1 and are National Board stamped

3. Price includes a seat & seal inspection per PHVO-2, Case 1.

All prices and technical details subject to change without notice.

For More Info:

Stephen Reimers 703-863-3871

Inventory of Pre-Owned Monoplace Chamber Systems

sdreimers1968@gmail.com

# **Marine Dynamics Chambers for Sale**

# Latest Update: December 3, 2025 by SDR

							10 Year Seat/Seal						
Item				Window	Door		Inspection	Computer	Window				
Number	Model & Color	Inside Dia.	Build Year	Year	Opens to	Cycles	Status	Status	Status	Avail.	Notes	List Price	FOB
673-1	42", White	42"			Interior		Due	Fuilly Manual	Original	4 wks.		\$12,500	West Coast
673-2	42" , White	32"			Interior		Due	Fuilly Manual	Original	4-6 wks.		\$12,500	West Coast
Notes:	Notes: 1. 180 day limited warranty. Requires post del'y installation and PM by tech acceptable to Seller.												

#### **General Notes to Marine Dynamics Listings:**

All chambers are steel shell with windows, with manual (crawl-in) type entry (like most diving chambers)

All chambers are built to ASME code shamped. Some are National Board Registerd and some are PVHO Stamped

All prices and technical details subject to change without notice.

1